

EXAMPLE OF RF MEASUREMENTS

	J1-J2	J1-J3	J4-J3	J4-J2
RETURN LOSS	-21.04	-20.61	-18.86	-19.99
INSERTION LOSS	-0.17	-0.18	-0.19	-0.18
ISOLATION	-85.45	-89.01	-90.17	-87.70

