


EXAMPLE OF RF MEASUREMENTS

	J01-J02	J01-J04	J03-J04	J03-J02
RETURN LOSS	-38.85	-42.30	-41.49	-38.96
I.L.	0.035	0.039	0.035	0.035
ISOL.	-74.23	-74.64	-75.56	-75.08



1.2 GHz

1.6 GHz