

EXAMPLE OF RF MEASUREMENTS

	J1-J2	J1-J3	J1-J4
RETURN LOSS	-16.52	-16.38	-16.67
I.L.	0.38	0.41	0.36
ISOL.	-83.57	-84.83	-84.19

