


EXAMPLE OF MEASUREMENTS

	J01-J02	J01-J04	J03-J04	J03-J02
RETURN LOSS	-39.20	-37.58	-45.26	-40.66
I.L.	0.042	0.043	0.046	0.041
ISOL.	-73.71	-75.30	-73.89	-74.84



1.2 GHz

1.8 GHz