




EXAMPLE OF RF MEASUREMENTS

Handwritten signature

RETURN LOSS		J1-J2	J1-J3	J4-J3	J4-J2
I.L.		-25.36	-27.17	-25.51	-24.77
ISOL.		0.124	0.133	0.132	0.146
	RETURN LOSS	-71.04	-74.35	-71.98	-74.67



7.0 GHz

8.5 GHz