

EXAMPLE OF RF MEASUREMENTS

SR

	J2-J1	J2-J3
VSWR	1.174	1.134
INSERTION LOSS	0.133	0.126
ISOLATION	-79.32	-77.20

