


EXAMPLE OF RF MEASUREMENTS

ST

	J1-J2	J1-J4	J3-J4	J3-J2
RETURN LOSS	-28.45	-30.03	-27.35	-30.00
I.L.	0.019	0.021	0.025	0.022
ISOL.	-68.3	-67.8	-68.1	-68.1



10.5 GHz

14.5 GHz